

## Z-2503 Dip Tube Evacuator Directions

1. Wear safety glasses! With some of these actions, there is a risk of paint splattering, especially to those unfamiliar with the process.
2. After filling the Universal solvent or water blend can with paint, turn can upside down and place it on top of the Z-2503.  
The head of the Z-2503 should mate with the valve on top of the aerosol can.
3. Press aerosol can down and hold for 3 seconds, which is how long it takes to clear the dip tube and valve of paint.
4. Remove aerosol can from Z-2503 and replace sprayhead. If Z-2503 becomes full of paint, please dispose of that paint responsibly.

